

National Transportation Safety Board Aviation Incident Preliminary Report

Location: Wichita, KS Incident Number: DCA14IA016

 Date & Time:
 11/21/2013, 2120 CST
 Registration:
 N780BA

 Aircraft:
 BOEING 747 - 409LCF
 Injuries:
 2 None

Flight Conducted Under: Part 121: Air Carrier - Non-scheduled

On November 21, 2013, about 2120 central standard time, a Boeing B747-400LCF (Dreamlifter) registered to Boeing Aircraft Holding Company, N780BA, and operated by Atlas Air Inc., as a 14 CFR Part 121 domestic cargo flight from John F. Kennedy International Airport, New York, New York, to McConnell Air Force Base, Wichita, Kansas, mistakenly landed at Colonel James Jabara Airport, Wichita, Kansas. Visual meteorological conditions prevailed, and an instrument flight rules flight plan was filed. There were no injuries to the two flight crew and the airplane was not damaged.

Aircraft and Owner/Operator Information

Aircraft Make:	BOEING	Registration:	N780BA
Model/Series:	747 - 409LCF 409	Aircraft Category:	Airplane
Amateur Built:	No		
Operator:	Atlas Air , Inc.	Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:		Operator Designator Code:	UIEA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Night
Observation Facility, Elevation:	IAB, 1400 ft msl	Observation Time:	0258 UTC
Distance from Accident Site:		Temperature/Dew Point:	12°C / 7°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	5 knots / , 130 $^{\circ}$
Lowest Ceiling:	None	Visibility:	10 Miles
Altimeter Setting:	29.88 inches Hg	Type of Flight Plan Filed:	IFR
Departure Point:	New York, NY (JFK)	Destination:	Wichita, KS (AAO)

Page 1 of 2 DCA14IA016

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	None	
Passenger Injuries:	N/A	Aircraft Fire:	None	
Ground Injuries:	N/A	Aircraft Explosion:	None	
Total Injuries:	2 None	Latitude, Longitude:	37.747500, -97.221111 (est)	
A dustrial tractions for the form and the				

Administrative Information

Investigator In Charge (IIC): John W Lovell

Additional Participating Persons:

Page 2 of 2 DCA14IA016